

南大阪線全車一覽

2007年04月01日現在

記号	車両番号					両数	所属	検修	記号	車番				両数	所属	検修	記号	車番				両数	所属	検修
(南大阪線特急車両)																								
Y05	16005	16105	2	7	1			U01	6301	6351	6202	6201	4	7	1	Mi01	6501	6401	2	7	1			
Y06	16006	16106	2	7	1			U03	6303	6362	6204	6203	4	7	1	Mi02	6502	6402	2	7	1			
Y07	16007	16107	2	7	1			U05	6303		6206	6205	3	7	1	Mi03	6503	6403	2	7	1			
Y08	16008	16151	2	7	1			U07	6304		6208	6207	3	7	1	Mi04	6504	6404	2	7	1			
Y51		16051 16108	2	7	1			U09	6305		6210	6209	3	7	1	Mi05	6505	6405	2	7	1			
Y09	16009	16109	2	7	1			U11	6306		6212	6211	3	7	1	Mi06	6506	6406	2	7	1			
Y11	16011	16111	2	7	1			U13	6307	6353	6214	6213	4	7	1	Mi07	6507	6407	2	7	1			
								U15	6308	6354	6216	6215	4	7	1	Mi08	6508	6408	2	7	1			
SL01	26401	26301 26201 26101	4	7	1			U17	6309	6355	6218	6217	4	7	1	Mi09	6509	6409	2	7	1			
SL02	26402	26302 26202 26102	4	7	1			U19	6310		6220	6219	3	7	1	Mi10	6510	6410	2	7	1			
								U21	6311		6222	6221	3	7	1	Mi11	6511	6411	2	7	1			
YS01	16501	16401	2	7	1										Mi12	6512	6412	2	7	1				
YS02	16502	16402	2	7	1										Mi13	6513	6413	2	7	1				
															Mi14	6514	6414	2	7	1				
															Mi15	6515	6415	2	7	1				
								C23	6122		6024	6023	3	7	1	Mi16	6516	6416	2	7	1			
								C25	6123		6026	6025	3	7	1	Mi17	6517	6417	2	7	1			
															Mi18	6518	6418	2	7	1				
								C29	6125	6163	6030	6029	4	7	1	Mi19	6519	6419	2	7	1			
								C31	6126		6032	6031	3	7	1	Mi20	6520	6420	2	7	1			
								C33	6127		6034	6033	3	7	1	Mi21	6521	6421	2	7	1			
								C35	6128		6036	6035	3	7	1	Mi22	6522	6422	2	7	1			
(南大阪線一般車)																								
FT01	6701	6601	2	7	1										Mi23	6523	6423	2	7	1				
FT02	6702	6602	2	7	1			C39	6130	6166	6040	6039	4	7	1	Mi24	6524	6424	2	7	1			
FT03	6703	6603	2	7	1			C41	6131		6042	6041	3	7	1	Mi25	6525	6425	2	7	1			
FT04	6704	6604	2	7	1			C43	6132	6167	6044	6043	4	7	1	Mi26	6526	6426	2	7	1			
								C45	6133	6168	6046	6045	4	7	1	Mi27	6527	6427	2	7	1			
								C47	6134	6169	6048	6047	4	7	1	Mi28	6528	6428	2	7	1			
MT21	6721	6671 6771 6621	4	7	1			C49	6135	6170	6050	6049	4	7	1	Mi29	6529	6429	2	7	1			
MT22	6722	6672 6772 6721	4	7	1			C51	6136	6171	6052	6051	4	7	1	Mi30	6530	6430	2	7	1			
MT23	6723	6673 6773 6821	4	7	1			C53	6137		6054	6053	3	7	1	Mi31	6531	6431	2	7	1			
MT24	6724	6674 6774 6921	4	7	1			C55	6138		6056	6055	3	7	1	Mi32	6532	6432	2	7	1			
MT25	6725	6675 6775 7021	4	7	1			C57	6139		6058	6057	3	7	1	Mi33	6533	6433	2	7	1			
MT26	6726	6676 6776 7121	4	7	1			C59	6140		6060	6059	3	7	1									
MT27	6727	6677 6777 7221	4	7	1			C61	6141		6062	6061	3	7	1									
								C63	6142		6064	6063	3	7	1									
AY21	6921	6821	2	7	1			C65	6143		6066	6065	3	7	1									
AY22	6922	6822	2	7	1			C67	6144		6068	6067	3	7	1									
								C69	6145	6172	6070	6069	4	7	1									
								C71	6146		6072	6071	3	7	1									
								C73	6147		6074	6073	3	7	1									
								C75	6148		6076	6075	3	7	1									
								C77	6149		6078	6077	3	7	1									

総数 持急車 26  
 一般車 190  
 合計 216